
From: jeffrey E. <jeevacation@gmail.com>
Sent: Wednesday, February 15, 2017 9:28 PM
To: Larry Visoski
Subject: Re: Nautica

great, please show me a photo of the aft side of boat, do we need to put another bench seat across the rear?

On Wed, Feb 15, 2017=at 4:25 PM, Larry Visoski <[REDACTED]> wrote:

Jeffrey
Good news,, we only Spun the prop hub on one engine,,
It's the rubber insert in prop,, so there is no internal issue with eng=ne,,
Need O2 sensors change in engines and small tune up and update for computer=,

Sent from my iPhone

--
=div class="gmail_signature" data-smartmail="gmail_signature">
please note

The=information contained in this communication is confidential, may be att=rney-client privileged, may constitute inside information, and is inten=ed only for the use of the addressee. It is the property of JEE U=authorized use, disclosure or copying of this communication or any part=thereof is strictly prohibited and may be unlawful. If you have receive= this communication in error, please notify us immediately by return=e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and al= copies thereof, including all attachments. copyright -all rights reser=ed

--001a11c164b2d5f56a0548985bd9-- conversation-id 53441 date-last-viewed 0 date-received 1487194096 flags 8590195713 gmail-label-ids 7 remote-id 688167