

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Friday, February 10, 2017 11:03 PM  
**To:** Jeffrey  
**Subject:** Je vacation; Rich Kahn  
Nautica update

Jeffrey

Appears fuel leak is Right side tank,, we drain the fuel that spilled in the=keel area, so the tank structure integrity is good,.

Fuel spill must have occurred during fueling, either main fuel line to tank o= the vent is suspected,.

Access is challenging however we are back at the fiberglass repair shop so r=pair will be easy, Kent our mechanic will try to work further tomorrow on t=e boat if he needs assistance he will call in a fuel tank specialist on Mon=ay morning I will keep all the devised

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">

```
<plist version=.0">
<dict>
  <key>conversation-id</key>
  <integer>53994</integer>
  <key>date-last-viewed</key>
  <integer>0</integer>
  <key>date-received</key>
  <integer>1486767774</integer>
  <key>flags</key>
  <integer>8590195713</integer>
  <key>gmail-label-ids</key>
  <array>
    <integer>2</integer>
  </array>
  <key>remote-id</key>
  <string>686781</string>
</dict>
</plist>
```