
From: Larry Visoski [REDACTED]
Sent: Tuesday, January 17, 2017 7:00 PM
To: Je vacation
Subject: Update

Gulfstream found faulty cabin temperature selector Rheostat faulty, part arrives tonight and will be changed, difficult change but we should be ready to fly tomorrow evening or Thursday morning at the latest return to service Good find!

Sent from my iPhone<?xml version="1.0" encoding="UTF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">

<plist version="1.0">

<dict>

<key>conversation-id</key>

<integer>56481</integer>

<key>date-last-viewed</key>

<integer>0</integer>

<key>date-received</key>

<integer>1484679624</integer>

<key>flags</key>

<integer>8590195713</integer>

<key>gmail-label-ids</key>

<array>

<integer>2</integer>

</array>

<key>remote-id</key>

<string>679505</string>

</dict>

</plist>