
From: Richard Kahn <[REDACTED]>
Sent: Thursday, December 15, 2016 12:31 AM
To: jeffrey E.
Subject: Fwd: TSG update

how can system can run so far off course...
i =ill question tomorrow when i speak with Bob..
not =ure why Brice could not come to this conclusion with Bob 2 weeks =go...

Richard Kahn
HBRK Associates Inc.
575 Lexington =venue 4th Floor
New York, NY 10022

[REDACTED]

Begin forwarded message:

From: =/b>Ann Rodriguez <[REDACTED]>

Subject: =/b>Re: TSG =pdates?

Date: =/b>December 14, 2016 at 5:24:08 PM =ST

To: =/b>Richard Kahn <[REDACTED]>

The main valve with 4 membranes were seized =hut, the membranes were severely corroded and the end cap needed to be =hanged.

Bob told us that if the membranes tested 800 =hen it would be normal and if it test 1000 then it would be bad. Our =ain membranes tested 7000 which is pure salt water that was =ontaminating the cistern water.

Tomorrow morning at 10am =ob will come out to rebuild the manifold, change the port adapter and =ork on the intake under the dock. After the maintenance service is done =t will still run manually but the water will be purifying properly.

Bob will send a report tomorrow =fternoon.

Ann R.

On Dec 14, 2016, at 4:42 =M, Richard Kahn <
<mailto:[REDACTED]>> wrote:

Richard Kahn
HBRK Associates =nc.
575 Lexington Avenue 4th Floor
New =ork, NY 10022



=