
From: Larry Visoski <[REDACTED]>
Sent: Wednesday, November 4, 2015 2:39 PM
To: Je vacation
Subject: Fuel

Jeffrey

We removed the fwd panel by landing light lens,, no obvious source of leak. P=te will remove filet panel upper portion of wing to Fusalge,, appears fuel is coming from upper portion of wing under fuselage. This Will be time consum=ng repair locating its source.

Fuel leak has slowed to a drip every 2 to 3 seconds now. Still shouldn't lea=,. Gulfstream maintenance Manuel allows a one drip per 30 seconds.

Bill would arrive Palm beach at 6pm tonight, -Should Dave and I head to PBI now and bring Boeing to Newark tonight?

Thx
Larry

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>

<key>date-last-viewed</key>
<integer>0</integer>
<key>date-received</key>
<integer>1446648221</integer>
<key>flags</key>
<integer>8590195713</integer>
<key>gmail-label-ids</key>
<array>
<integer>7</integer>
</array>
<key>remote-id</key>
<string>560235</string>

</dict>
</plist>