

---

**From:** Eric Roth [REDACTED]  
**Sent:** Tuesday, December 10, 2013 8:36 PM  
**To:** 'Jeffrey Epstein'  
**Subject:** RE:  
**Attachments:** image001.jpg; image002.jpg; image003.jpg

</=:p>

</=:p>

Air Gaspers - =o:p>

Squawk: =abin area air gaspers do not seat 100% and the pressure causes a =#8220;hissing sound".

Status: Larry has procured gaspers =nd plenums. We noticed that they did not come with the wire clamps, =o we will have to order them for you. We shipped one gasper =overnight to Larry for delivery on 12/10 so that he may show it to you =o identify if you want them plated or not.

Est. Time Required: Metal plating =ill take approximately 10 – 12 days. Once gaspers are ready =or installation, IJI will require 3 -4 days to trim escutcheons and =nstall the gaspers.

Upwash Lighting-

Squawk: Various light fixtures are =ntermittent.

Status: Each light bulb and =ssociated power supply ballast will need to be tested. IJI recommends =eplacing the light bulbs as a means of testing and perhaps more =mportantly to have even coloration throughout the cabin.

Est. Time Required: IJI will require = – 2 days to troubleshoot. Dependent upon finding, it may take = – 3 days to correct.

R/H #2 VIP Master Switch =anel-

Squawk: Client would like to have the =/H #2 master switch panel reworked by manufacturer to have it =eprogrammed to control the shades "ALL UP" and "ALL =OWN".

Status: The switch panel was going to =e removed at Gulfstream and sent to the manufacturer for a return on =he 20th and I found out today that this is not going to =appen.

Est. Time Required: Manufacturer has =tated they will "commit" to a two (2) week turn around to =eprogram the panel and replace a few internal parts.

Window =hades-

Squawk: Pleated window shade material =ithin the window panel assemblies in the main cabin are =#8220;wrinkled" at the pleats.

Status: We sent an e-mail with =hoto's and waiting for vendors response including downtime =quired.

Est. Time Required: Waiting on =endor.

Table Lid-

Squawk: Client would like to route =he inboard vertical surface to provide an easier opening of lid.

Status: IJI has identified ½ moon =hape and rectangular shape. Need JE decision..

Est. Time Required: Route and paint =o coordinate – 2 days.

Maintenance Runner-

Squawk: Need to fabricate vinyl =aintenance runner.

Status: Waiting on color choice by =E.

Est. Time Required: 2 days after receipt of material (material should be in stock).

Fwd cabin Monitor-

Squawk: Fwd cabin monitor is faulty.

Status: Sent monitor to manufacturer for warranty. Replaced with temporary monitor which has been determined by Gulfstream Savannah to also be faulty. Informed manufacturer that client is very unhappy with this model and that he would like to move away from this model and replace it with a HD monitor.

Est. Time Required: Waiting on reply from manufacturer to see if they will accept the return and provide a credit towards a new HD monitor.

Entertainment System -

Squawk: JE wants to upgrade system.

Status: Larry is testing the Bose system to see if JE likes it.

Est. Time Required: Once JE has identified that he would like to move in this direction, we will prepare a quote including cost and time required.

=AO| PRESIDENT

=img width=205 height=58 id="Picture\_x0020\_1" =rc="cid:image001.jpg@01CEF5BD.75521220" alt="IJI Logo - horizontal-SMALL">

[REDACTED] =a href="mailto:[REDACTED]@intljet.com-----  
----- =----- =o:p>

From:=/b> Jeffrey Epstein [mailto:jeevacation@gmail.com]

Sent: Tuesday, December 10, 2013 3:37 PM

To: Eric Roth; Ivjet; Richard Aahn

Subject:

you told me i would receive a detailed schedule either late yesterday or this morning, both have past

--=br>\*\*\*\*\*

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. Copyright -all rights reserved

=