

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Monday, December 2, 2013 7:35 PM  
**To:** jeevacation@gmail.com  
**Subject:** Update

Jeffrey, they are evaluating the measurements they have taking for the wing p=int thickness at this time. First opinion from the paint shop manager using=a sonar measuring device that the wing paint thickness is tremendously out o= limits. Once they have documented the measurements they will produce an av=rage on each surface on wings, flight controls, fuselage and tail, that wil= be presented to engineering department I should have engineering's review b= lunchtime tomorrow

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"

"http://www.apple.com/DTDs/PropertyList-1.0.dtd">

```
<plist version=.0">
<dict>
  <key>date-last-viewed</key>
  <integer>0</integer>
  <key>date-received</key>
  <integer>1386012927</integer>
  <key>flags</key>
  <integer>8590195717</integer>
  <key>gmail-label-ids</key>
  <array>
    <integer>27</integer>
    <integer>7</integer>
  </array>
  <key>remote-id</key>
  <string>367258</string>
</dict>
</plist>
```