
From: Eric Roth [REDACTED]
Sent: Wednesday, July 27, 2011 2:25 PM
To: 'Jeffrey Epstein'
Cc: [REDACTED]
Subject: Refurbishment Budgetary Guideline
Attachments: image001.jpg; JE Letter.pdf

Dear Jeffrey,

The attached letter identifies budgetary costs to refurbish a "general" GIVsp.

As discussed with Larry last week, floor plan modifications on a GIVsp are a lot less expensive than a GV due to less stringent engineering and certification (The GIVsp falls under 9g certification whereas the GV is under the 16g regulations).

Let me know what else I can do for you?

Sincerely,

Eric Roth

President

International Jet Interiors

2221 Smithtown Avenue

Long Island MacArthur Airport

Ronkonkoma, NY 11779

[REDACTED] Phone

[REDACTED] Fax
[REDACTED] Cell

[REDACTED] <mailto:[REDACTED]> =nbsp; e-mail

www.intljet.com website

=