
From: brice gordon <[REDACTED]>
Sent: Friday, October 28, 2011 6:33 PM
To: jeevacation@gmail.com
Cc: Rich Kahn; Darren Indyke; Gary Kerney
Subject: LSJ Transformer
Attachments: Transformer1.jpg; transformer2.jpg

update:

we have shut down the transformer and are running on Generator power Oil level is indicated at empty, to fill would require 530 gallons of non inhibited mineral oil Estimated Cost \$900.00 @ 55 gallons = \$8700.00 Mike Glidden will be forwarding options for repair and/or replacement early next week please note the following:
To repair will require removal and shipping to Florida Transformer was built to design spec, New transformer will be stainless steel spec Investigating alternative oil price

--

Brice Gordon
Little Saint James
USVI
Phone: [REDACTED] <tel:340%20513%209855>