
From: BMG <[REDACTED]>
Sent: Friday, February 3, 2012 2:18 AM
To: J Epstein
Cc: [REDACTED]
Subject: Re:

Power steering fixed

Ran Sunday and had a oil temp alarm on engine 1 Believe it is a faulty sensor Plan to swap sensor to engine 2 to confirm
FYI outside of this , this hull rode 6ft seas with no problem Will bring to LSJ for weekend

Brice

Sent from my iPhone

On Feb 2, 2012, at 8:34 PM, [REDACTED] > wrote:

> JE is asking when midnight express is going to be ready.
<?xml version="1.0" encoding="UTF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version="1.0">
<dict>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1328235476</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>27</integer>
 <integer>7</integer>
 </array>
 <key>remote-id</key>
 <string>204545</string>
</dict>
</plist>