
From: Eric Roth [REDACTED]
Sent: Thursday, February 13, 2014 6:46 PM
To: 'Jeffrey Epstein'
Cc: 'Larry Visoski'; 'Jay Massar'
Subject: Window insulation
Attachments: image002.jpg; image004.jpg; image006.jpg; photo 2.jpg; photo 1.jpg

Jeffrey,=/o:p>

</=:p>

"photo2.jpg" is of the existing window insulation. This was typical =f all of the windows. This was a piece of foam that sealed the =ircraft of only 1/3 of the window, the rest was without any insulation =t all, exposing the clear desiccant tubes.

</=:p>

"photo1.jpg" is of the newly installed insulation. We removed the =ld insulation that only treated 1/3rd of the window and =nstalled the new open cell foam insulation around the total =nbsp;perimeter, being especially careful not to "pinch" the =esiccant tubing.

</=:p>

We are =rying to keep things moving as quickly as possible to maintain the =chedule.

</=:p>

</=:p>

</=:p>

</=:p>

</=:p>

</=:p>

</=:p>

</=:p>

</=:p>

=nbsp;| PRESIDENT

----- =----- =o:p>

2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779

=