
From: Larry Visoski [REDACTED]
Sent: Wednesday, April 27, 2016 1:43 PM
To: Je vacation
Cc: Rich Kahn
Subject: GIV update

Jeffrey

Pete informs the FAMV "Fan Air Modulation Valves" where swapped last night, it's was a big job, the mechanics also located filter in Regulator valve that is mounted on top of Fan Air valve, once they removed the filter, they noted a metal filter screen on the R/H Air side of the Regulator valve with obstruction or FOD, "Foreign Object Debris" they put the screens in Ultra Sound-cleaner and reinstalled, Pete didn't feel the obstruction was large enough to effect operation,

Ground runs / ops check this afternoon,

WiFi box in Tail compartment appears to have failed again, since SatPhone and WiFi didn't work on yesterday flight, this will be warranty exchange,

Will keep you advised

Thx
Larry

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1461764567</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>7</integer>
 </array>
 <key>remote-id</key>
 <string>607317</string>
</dict>
</plist>