
From: SCOTT DENETT [REDACTED]
Sent: Tuesday, October 22, 2013 2:01 AM
To: J Epstein; Rich Barnett
Subject: Fwd: Revised Invoice
Attachments: image003.jpg; Untitled attachment 00161.htm; Inv_E2109_Scott Denett.pdf; Untitled attachment 00164.htm

my =dvise is get this done asap with JE approval (got kinda one go from =ou in front of B Goodman) but if you could turn this into a =ormal OK

I think this will be the go to =uys for your 71st property for years to =ome

once its working we can look for a =better marantz" bet I think the key here Jeffrey is when i was working =ith this tek he pointed out what a good combo the marantz and sunfire =as with your lucas Dobly system

so I =hink you should go for it I spent hours with the owner this =ill lead to good things

your call let us =now

thx

scott

sorry for the =ypos

=div>Begin forwarded message:

From: Radek BHT [REDACTED]

Subject: Revised Invoice

Date: September 10, 2013 =:50:03 AM EDT

To: sdenett@mac.com

Cc: 'Kerry Bright' =lt;kerry@brighthometheater.com

Morning Scott,

Here is a revised =nvoice

Technical opinion :

Existing setup has multiple =ssues :

1) Electrical circuit needs to =e inspected, given the fact 2 AVR=blew within couple of month, there might be some =strange spikes or shorts in the electrical feed

Existing Monster Cable power =conditioners are not surge protectors and will not protect the equipment in case of =electrical spikes - I recommend to replace it with new generation of =urge protectors from Surgex

[ht=p://www.surge.com/pdf/residential/XR115-Brochure-EMAIL.pdf](http://www.surge.com/pdf/residential/XR115-Brochure-EMAIL.pdf)

2) Crestron - this system is not =very stable and requires frequent maintenance

RTI control is user =riendly with very solid performance at half a cost

This is latest, just introduced, =product

http://www.rticorp.com/files/cutsheet_t2x.pdf

3) Shutters and lights =/span>

Shutters control is very simple = contact closure control, we can implement easily

Lights - I could not find a Main =peater (the brain) of the system, we need to determine what system is used - =utron Radio Ra 1st generation or Radio Ra2

Difference is in the drivers (=lder drivers might not work with new control system)

4) BluRay - this system deserves =etter BluRay - existing entry level Sony will not output best possible HD =icture, we suggest to get oppo BluRay - one of the best BluRay manufacture ever.

<http://www.oppodigital.com/blu-ray-bdp-103/>

We are very concerned about the =VRs blowing up.

It might also be caused by short =n speaker wiring

Since we will not be able =o replace them, we will not take responsibility for the recurring AVR =ssues

Let me know if you have any question

Thank You

Radek Nesnidal

Custom =ntegrator

Bright Home =heater

202 Ave A

New York, NY, =0009

www.brighthometheater.com

O:

C:

=