
From: Eric Roth <[REDACTED]>
Sent: Tuesday, May 16, 2017 3:31 PM
To: Richard Kahn
Cc: jeffrey E.; [REDACTED]
Subject: Crew Privacy Curtain

Richard,

Larry just informed me that the aircraft does NOT have a crew privacy curtain.

Please note and DELETE this item from our proposal.

211 Crew Privacy Curtain \$2,022 </=>

The crew privacy curtain will be replaced. Fabricate one (1) curtain with customer-approved material. The curtain will be retained through use of rare earth magnets and an embedded metal strip in the curtain to keep the curtain tight against the bulkhead.

Best Regards,

Eric

ERIC H. ROTH<=> | PRESIDENT

P</=pan> [REDACTED] | C=/b> [REDACTED] | [REDACTED] | www.intljet.=om
<http://www.intljet.com/> <http://twitter.com/#!/intljet> <http://www.facebook.com/intljet>

2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=:p>