
From: Larry Visoski [REDACTED]
Sent: Friday, December 4, 2015 12:28 AM
To: Je vacation
Subject: Update

Jeffrey

Just ran Engines and completed Precooler ground checks,, no defects noted,, -no fluctuations in voltage or psi today,, - we are going to install new controller on right side, since it's original c=st \$2400.,

Since we had no fluctuations on the ground we would like to accomplish short=uts like tomorrow at noon.

Is short 20min test flight ok with Pete ?

Thx
Larry

```
Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
    <key>date-last-viewed</key>
    <integer>0</integer>
    <key>date-received</key>
    <integer>1449188884</integer>
    <key>flags</key>
    <integer>8590195713</integer>
    <key>gmail-label-ids</key>
    <array>
        <integer>5</integer>
    </array>
    <key>remote-id</key>
    <string>567778</string>
</dict>
</plist>
```