

---

**From:** Richard Kahn <[REDACTED]>  
**Sent:** Wednesday, June 24, 2015 8:18 PM  
**To:** jeffrey E.  
**Subject:** Re: Dock Fenders

ok thank you  
regarding hole placement in fenders would you like every 1.5 feet or every foot please advise thank you

Richard Kahn  
HBRK Associates Inc.  
575 Lexington Avenue 4th Floor  
New York, NY 10022  
[REDACTED]

On Jun 24, 2015, at 2:17 PM, jeffrey E. <jeevacation@gmail.com> wrote:

option 3

On Wed, Jun 24, 2015 at 1:38 PM, Richard Kahn <[REDACTED]> wrote:

Richard Kahn  
HBRK Associates Inc.  
575 Lexington Avenue 4th Floor  
New York, NY 10022  
[REDACTED]

Begin forwarded message:

**From:** Richard Kahn <[REDACTED]>  
**Subject:** Dock Fenders  
**Date:** June 23, 2015 at 3:44:00 PM EDT

To: =/b>"jeffrey E." <jeevacation@gmail.com>

## Layout

=/span>

Attached are 5 layout options for dock =enders in addition to our current layout

Options 1-3 are three rows of 6' =enders

pieces)  
Carlos measured to cover entire dock we =ould need 693 feet which comes to 116 (6'

Options 4 & 5 are =wo rows of 6' fenders

=ieces)  
Carlos measured to =over entire dock we would need 462 feet which comes to 77 (6'

Note 500 feet is minimum =rder therefore we will need to order 84 pieces

Carlos has sample on LSJ =n dark grey color which you said was correct color

=onfiguration  
If you are not satisfied =ith any of the above layouts please advise on alternate

## Fender Holes

Regarding Holes =n Fenders i also outlined two options

Option A - Screws will be 1.5 feet =part

Option B - Screws will be 1 foot =part

The Back =ole would be 1/2" and Front Hole will be 1.5"

## Timing

Production will take 3 weeks and then another 1 week for =hipping

Projected arrival on STT is July =0

## Installation

Carlos said that with Ramon and =ernando installation will take approximately 1 week

## Projected Costs

= 9,314.92  
Options 1-3 (three rows =f fenders) Color - Dark Grey # 11181 =/span> 13.44 x 693 feet

Vendor Hole Drilling (1 drilling cost per hole x 116 pieces = 3 holes) = 348.00  
 Stainless Steel Threaded Rods & Bolts =estimated 116 pieces x 3 screws per piece x 12.00) 4,176.00 =

Tropical =hipping = = 1,500.00  
 Miscellaneous=Tools (drill bits, etc) = = 661.08  
 Total Cost with three rows of =enders = =nbsp; 16,000.00

Options 4 & 5 (two rows of fenders) Color - Dark Grey # =1181 =/span> 13.44 x 500 feet  
 = 6,720.00

Vendor Hole Drilling (1 drilling cost per hole x 84 pieces x = holes) = 252.00 =/span>  
 Stainless Steel Threaded Rods & Bolts =estimated 84 pieces x 3 screws per piece x 12.00)  
 3,024.00 =

Tropical =hipping = = 1,500.00  
 Miscellaneous=Tools (drill bits, etc) = = 504.00  
 Total Cost with three rows of =enders = =nbsp; 12,000.00

Please advise on which Option you would like in addition to =umber of holes per piece  
 (3 or 4)

[http://www.zoro.com/value-brand-threaded-rod-plain-12-10x3-ft-l=01201003pldar/i/G1605527/?utm\\_source=google\\_shopping&utm\\_medium=c=c&utm\\_campaign=Google\\_Shopping\\_Feed&gclid=CjwKEAjwh6SsBRCYrKH=7J3NjicSJACUxAh7poTcc2K3zsySvFqwmGLzK3TUQ52UwvFjuxcOQ-Lh5hoCFKnw\\_wcB&=clsrc=aw.ds](http://www.zoro.com/value-brand-threaded-rod-plain-12-10x3-ft-l=01201003pldar/i/G1605527/?utm_source=google_shopping&utm_medium=c=c&utm_campaign=Google_Shopping_Feed&gclid=CjwKEAjwh6SsBRCYrKH=7J3NjicSJACUxAh7poTcc2K3zsySvFqwmGLzK3TUQ52UwvFjuxcOQ-Lh5hoCFKnw_wcB&=clsrc=aw.ds)

<http://technorubberindustries.com/techno.pdf>

Richard Kahn  
 HBRK Associates Inc.  
 575 Lexington =venue 4th Floor  
 New York, NY 10022  
 tel =a href="tel:212-971-1306" value="+12129711306" target="\_blank" =lass="">212-971-1306

fax 646-350-0954 <tel:646-350-0954>  
 cell 917-414-7584 <tel:917-414-7584>

<=blockquote>

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

=