
From: [REDACTED]
Sent: Friday, March 4, 2011 5:51 AM
To: Je vacation

Ok, they found a very loose wire on cannon plug to surge valve, I practically came out of connector, we are going to re secure and try apu, I'll believe it after I hear the start, if that makes a difference,. No bets, Sent via BlackBerry by AT&T

```
<?xml version="1.0" encoding="UTF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
```

```
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
```

```
<plist version="1.0">
```

```
<dict>
```

```
  <key>date-last-viewed</key>
```

```
  <integer>0</integer>
```

```
  <key>date-received</key>
```

```
  <integer>1299217872</integer>
```

```
  <key>flags</key>
```

```
  <integer>8590195713</integer>
```

```
  <key>gmail-label-ids</key>
```

```
  <array>
```

```
    <integer>5</integer>
```

```
    <integer>18</integer>
```

```
  </array>
```

```
  <key>original-mailbox</key>
```

```
  <string>imap://jeevacation@imap.gmail.com/%5BGmail%5D/All%20Mail</string>
```

```
  <key>remote-id</key>
```

```
  <string>139143</string>
```

```
</dict>
```

```
</plist>
```