
From: Carlos Rodriguez [REDACTED]
Sent: Wednesday, April 29, 2015 1:09 PM
To: Ann Rodriguez; Jeffrey Epstein
Subject: Little C

Greetings Sir,&nb=p;

This morni=g on the way to LSJ the boat began to take on water on the starboard hull.= The bilge pumps couldnt keep up and we barely made it to the dock. &=bsp;l truly believe the collision this boat sustained caused structural da=age asides from what was repaired. The boat has a lot more flex than=it used to and also the top deck and hull portions shift and flex ,this be=gn a secondary effect of the collision. We are taking LC to the boat=ard asap to see what option we got for repair.

respectfully
Carlos