
From: Richard Kahn [REDACTED]
Sent: Thursday, January 14, 2016 10:13 PM
To: jeffrey E.
Subject: Fwd: Mr. Christopher Trackhoe

we will source other trackhoes ASAP

Richard Kahn
HBRK Associates Inc.
575 Lexington Avenue 4th Floor
New York, NY 10022
tel =12-971-1306
fax 646-350-0954
cel [REDACTED]

Begin forwarded message:

From: =/b>Ann Rodrique [REDACTED]
Subject: =/b>Mr. Christopher Trackhoe
Date: =/b>January 14, 2016 at 4:49:26 PM =ST
To: =/b>Rich Kahn <[REDACTED]>

Hi Rich,

I just called Jules to confirm the issues with the Trackhoe and he said the lead is cracked on the Engine and its blowing a lot of black smoke.

I hope Mr. Christopher is not waiting for the engine to blow completely while it's in our possession because I don't want him to say it was our fault in anyway. Jules said that Andy need to replace the Engine real soon.

Ann =.

=