

---

**From:** Bgordon.lsj@gmail.com <[REDACTED]>  
**Sent:** Tuesday, April 12, 2011 6:23 PM  
**To:** Richard Kahn  
**Cc:** Jeffrey Epstein; Emad Hanna  
**Subject:** Re: FEDEX and parts

Yes

thats why we had in stock a spare probe but unfortunately it was faulty We also have belts filters and valve controller on sight

Sent from my iPhoneE

On Apr 12, 2011, at 11:40 AM, Richard Kahn <[REDACTED]> wrote:

> how was \$150 determined?  
> was it a quote from fed ex based on weight or guess?  
> is this something we should be keeping spare parts for?  
> thank you  
>  
> Richard Kahn  
> HBRK Associates Inc.  
> 301 East 66th Street, Suite 10F  
> New York, NY 10065  
> tel [REDACTED]  
> fax [REDACTED]  
> cell [REDACTED]

>  
> On Apr 12, 2011, at 11:36 AM, brice gordon wrote:

>  
>> Jeffrey  
>> i need to FEDEX 3 temperature sensors for the chiller unit at the  
>> library= one has failed and the replacement we had in stock is faulty  
>> without this we cannot maintain temperature in library Cost is approx  
>> \$150.00  
>>  
>>  
>>--  
>> Brice Gordon  
>> Little Saint James  
>> USVI  
>> Phone: [REDACTED]  
>>  
>  
<?xml version=.0" encoding=TF-8"?>  
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">  
<plist version=.0">  
<dict>  
    <key>date-last-viewed</key>

```
<integer>0</integer>
<key>date-received</key>
<integer>1302632491</integer>
<key>flags</key>
<integer>8623750145</integer>
<key>gmail-label-ids</key>
<array>
    <integer>5</integer>
    <integer>18</integer>
</array>
<key>original-mailbox</key>
<string>imap://jeevacation@imap.gmail.com/%5BGmail%5D/All%20Mail</string>
<key>remote-id</key>
<string>148730</string>
</dict>
</plist>
```