

To: Je vacation[jeevacation@gmail.com]
Cc: [REDACTED]
From: lvjet@aol.com
Sent: Thur 6/10/2010 2:44:35 AM
Subject: Update

General dynamics is working G2 now, all point to a failed TR. If there is a part in Savanah, counter to counter earliest is 1030am they believe, but to early to tell at this point! More update later tonight, could be loose connection, but hardly believe that, they will call me at all hours tonight to keep me posted, I'm looking threw my maintenance manuals now to see what ties in the bus that is causing the seat belt chime to ring. And auto pilot to kick off, must be same inverter bus causing this to accure. there is a lot of auto switching in our inverter system, just a simple power source change would kick auto pilot off,!

Thx

Larry

Sent from my BlackBerry® wireless handheld