
From: jeffrey E. <jeevacation@gmail.com>
Sent: Thursday, May 3, 2018 9:42 PM
To: Brice
Subject: Re: LSJ Dock and Bumpers

ok and larger better barge dock

<=iv class="gmail_quote">

On Thu, May 3, 2018 at 5:23 PM b=ice gordon [REDACTED] > wrote:

The existing apron was comprised on both sides by the storms

Bo=h Mike and I are aware of what's under and how deep it was buried =here.

New electrical feeds will need to run for both shelters, a= it appears sea water has penetrated the electrical conduit

Instead of a just slab, proposing a buried bulk head formed ocean side to=protect slab and footings from being undermined again

Sent from my iPhone

On=May 3, 2018, at 5:06 PM, jeffrey E. <jeevacation@gmail.com <mailto:jeevacation@gmai=.com> > wrote:

=blockquote type="cite">

why destroy the whole area=C2 for four footings for the shed? there are ma=y things running under that area.

On Thu, May 3, 2018 at 4:25 PM Cashkim Bussue= [REDACTED] > wrote:

<https://ci3.googleusercontent.com/proxy/y-eEJVZO0Zxti=XuMmRjVZzxAGAwJupv74ajiF4CXmb6sur6K2QwkLXr7GMupOJtKP91SqftvjLoCJwE2ulPcY6K=RZBhXx1bEGr9pISY6roJZcq139mt0P8=s0-d-e1-ft#https://ssl.gstatic.com/docs=/oclist/images/icon_10_generic_list.png> IMG_6061.JPG=80

<https://ci3.googleusercontent.com/proxy/y-eEJVZO0ZxtirXuMmRj=ZzxAGAwJupv74ajiF4CXmb6sur6K2QwkLXr7GMupOJtKP91SqftvjLoCJwE2ulPcY6K1RZBhXx=bEGr9pISY6roJZcq139mt0P8=s0-d-e1-ft#https://ssl.gstatic.com/docs/doclist=images/icon_10_generic_list.png> IMG_6062.JPG

=E2

=C2 IMG_6063.JPG <https://drive.google.com/file/d/1G1=ja09IWwVuuBKRTg3rbArF-GaKNKsc/view?usp=drive_web>

IMG_6064.JPG <https://drive.google.com/file/d/1Xi9009C-ujBJbrFtdJOcTIMOOXbpabe-
/view?usp=drive_web>

IMG_6065.JPG
<https://drive.google.com/file/d/19qlwsDmPswz1hHHsGVH5dLerTxjSqlf4/view?usp=drive_web>

IMG_6066.JPG
<https://drive.google.com/file/d/1BEsdsd4UV0zCd9PvptcHe9RUqg875Vww/view?usp=drive_web>

<https://ci3.googleusercontent.com/proxy/y-
eEJVZO0Zxti=XuMmRjVZzxAGAwJupv74ajiF4CXmb6sur6K2QwkLXr7GMupOJtKP91SqftvjLoCJwE2ulPcY6K=RZBhXx1bEGr9
pISY6roJZcq139mt0P8=s0-d-e1-ft#https://ssl.gstatic.com/docs=/oclist/images/icon_10_generic_list.png>
IMG_6067.JPG</=>

=80
=A0IMG_6068.JPG
<https://drive.google.com/file/d/1RWwIK=7NUL5HFdcvYtohusUItImSqHNr/view?usp=drive_web>

<https://drive.google.com/file/d/1qQ5OTX8RBRzxpjDfbKtou=8A_VBSQ8mr/view?usp=drive_web>
IMG_60=0.JPG <https://drive.google.com/file/d/1IIUrBFWlhjml2_G0bkvllHDPJoVAD=aW/view?usp=drive_web>

IMG_6082.JPG
<https://drive.google.com/file/d/16jBkyWWbS_5t3fAZDYqt6bRsyCHsL6qh/view?usp=drive_web>

<https://ci3.googleusercontent.com/proxy/y-
eEJVZO0ZxtirXuM=RjVZzxAGAwJupv74ajiF4CXmb6sur6K2QwkLXr7GMupOJtKP91SqftvjLoCJwE2ulPcY6K1RZB=Xx1bEGr9p
ISY6roJZcq139mt0P8=s0-d-e1-ft#https://ssl.gstatic.com/docs/doclist/images/icon_10_generic_list.png> IMG_6083.JPG
=div class="gmail_chip gmail_drive_chip" style="width:396px;height:18px=max-
height:18px;background-color:#f5f5f5;padding:5px;color:#222;font-family:arial;font-style:normal;font-weight:bold;font-
size:13px;border:1px solid #ddd;line-height:1"> IMG_6084.JPG
<https://drive.google.com/file/d/11FZTOpvQcuJ=1s2FqaFxx-ugFuXeoqUi/view?usp=drive_web>

IMG_6085.JPG <https://drive.google.com/file/d/1Xjnwe_1-
ELs2ei97exxNsr537g61gzPI/view?usp=drive_web>

=a
href="https://drive.google.com/file/d/11GwY6ONPEwzCE6zdll7wWnvD3LOMq4F=/view?usp=drive_web"
style="display:inline-block;max-width:366px;overflow:hidden;text-overflow:ellipsis;white-space:nowrap;text-
decoration:none;padding:1px 0;border:none" target="_blank"> <https://ci3.googleusercontent.com/proxy/y-
eEJVZO0ZxtirXuMmRjVZzxAGAwJupv74ajiF4CXmb6sur6K2QwkLXr7GMupOJtKP91SqftvjLoCJwE2ulPc=6K1RZBhXx1bEGr9
pISY6roJZcq139mt0P8=s0-d-e1-ft#https://ssl.gstatic.com/docs/doclist/images/icon_10_generic_list.png>
IMG_6086.JPG

=E2
=C2 IMG_6087.JPG <https://drive.google.com/file/d/1H4=PF4Z3nll3-
A2hruyhHn7kwomtDwby/view?usp=drive_web>

IMG_6090.JPG <https://drive.google.com/file/d/18m5gRo7fG-
MQlakWslRzWioiRMjJCIn0/view?usp=drive_web>

IMG_60=1.JPG
<https://drive.google.com/file/d/1TsSeYOSHpnBthlCG0W_=J0nqtWmN64ur/view?usp=drive_web>
IMG_6092.JPG <https://drive.google.com/file/d/1Z2NLT0JmT8GN1AZd3p-
yfDTwkl8rBHn/view?usp=drive_web>

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

-- =br>

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--94eb2c11e478367950056b541209-- conversation-id 7475 date-last-viewed 0 date-received 1525383709 flags 8590195713 gmail-label-ids 7 remote-id 818915