
From: jeffrey E. <jeevacation@gmail.com>
Sent: Monday, May 2, 2016 9:18 PM
To: Larry Visoski
Subject: Re: Scan from Meridian Jet Center

should not be constant voltage throughout run, need to talk to tech ,

On Mon, May 2, 2016 at 2:49 PM, Larry Visoski <[REDACTED]> wrote:

Jeffrey

Pete informs that zero or lower voltage may only be seen with Takeoff power,
Since that is hottest air going thru Precooler,

Sent from my iPhone<=div>

Begin forwarded message:

From: Pete Rawson <[REDACTED]>
Date: May 2, 2016 at 2:02:45 PM AST
To: [REDACTED] <lvjet@aol.com>
Subject: FW: Scan from Meridian Jet Center

Hi Larry,=br>Here are the readings that I got after the fan air valve swap.
These are before the filter unit changes.

We only went to 90%, and didn't wait for a response.
I'm sure that the readings would have changed if we waited.=/span>

I'll talk to Gulfstream tomorrow.

Regards,
Pete

-----Original Message-----

From: Meridian Jet Center <[REDACTED]>
Sent: Monday, May 02, 2016 1:55 PM
To: Pete Rawson <[REDACTED]>
Subject: Scan from Meridian Jet Center

Please open the attached document. It was scanned and sent to you from Meridian Jet Center.

Number of Images: 2

Attachment File Type: PDF

Device Name: Meridian Jet Center

Device Location:

For more information, please visit <http://www.meridian.aero/> <<http://www.meridian.aero/>>

=/div>

--

=C2◆ please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved