
From: Larry Visoski <[REDACTED]>
Sent: Wednesday, March 30, 2016 1:46 AM
To: Je vacation
Subject: GIV voltage

Jeffrey

The voltage and PSI readings are tied to Heat Exchanger in pylon, PSI and Voltage control 400 Degree air utilizing heat exchanger in pylon.

Gulfstream will continue to trouble shoot the Voltage pulse when they run engines tomorrow.

I'll have better explanation tomorrow,

Thx
Larryv

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>84742</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1459302373</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>600098</string>
</dict>
</plist>