
From: Larry Visoski [REDACTED]
Sent: Monday, April 2, 2018 11:18 PM
To: Jeffrey [REDACTED]
Subject: Veneer

Jeffrey

Gulfstream informs they would need to order more veneer from vendor if you replace the Cabin side of pocket door, and also cabin side of aft Lav door,. The remaining veneer located in Savannah is not enough to accomplish these panels., Gulfstream wants to make sure the Pattern of the replaced veneer matches the L/H and R/H sides of fwd bulkhead panels. Note, Eric's process for finishing differs from Gulfstream, as we seen in the Silver Beach samples you first selected.

Should I tell Gulfstream to place the order for more veneer?

Thx
Larry

Sent from my iPad=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>10740</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1522711071</integer>
 <key>flags</key>
 <integer>8590195717</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>6</integer>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>809034</string>
</dict>
</plist>