
From: Leighton Allenby [REDACTED]
Sent: Friday, August 21, 2015 1:03 PM
To: Jeffrey Epstein
Cc: NYC - Richard Kahn; Leighton Allenby
Subject: Radar on Big N repair or replace

Hello Mr. Epstein,
The radar on Dig N isn't workin=. Keeps blowing fuses.

Two options

1. Send radar to Furuno in Maryland to inspect & give estimate =o repair

1. They think its a power filter board failure - cost is=\$450. for board plus \$100 per hr labor to test and fix
2. Shipping 3-=ay priority is \$61.95 each way
3. Total Approx. cost is \$700. to \$850= to fix (if they determine it is unfixable then we only occur the shipping=charge of \$61.95 one way/no disposal fee

2. Cost of n=w Furuno 1835 digital model

1. <http://www.furunousa.com/Prod=cts/ProductDetail.aspx?product=1835>
<<http://www.furunousa.co=/Products/ProductDetail.aspx?product=1835>>
2. Retail cost is \$4,895.</=i>
3. Amazon price is \$3,867. - if we go with this option I look look for =est price once a decision is made

suggest to try to fix=option 1 and if unrepairable go with option 2

Whi=h option do you want to proceed with?

<=iv>

Best,
Leighton

<=font>

=eighton Allenby
Director of Properties

