
From: Larry Visoski <[REDACTED]>
Sent: Sunday, August 9, 2015 4:05 PM
To: Je vacation
Subject: Mounts
Attachments: IMG_3519.PNG; Untitled attachment 00478.txt

Jeffrey

I'd like your opinion,,

Picture below is upper isolation mount that was changed in Islip January 201=., note the compression at the bottom of isolator, we can rotate 180 degree= which is approved or install new, price \$1,700 each.

We have 4 of these per side,, 2 fwd and 2 aft,, this is the most visible of i=olators,,

Should I install new as required, rotate 180 degrees or install all new ones=

Thx
Larry

I received your email to Kathleen,, I sent,,