

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Monday, July 13, 2015 7:47 PM  
**To:** Ann Rodriquez  
**Subject:** Re: Big N

replace

On Mon, Jul 13, 2015 at 3:44 PM, Ann Rodriquez <[REDACTED]> wrote:

=/div>  
Good Afternoon Anna

I came back on Island today and reviewed progress on Big ,all looks gre=t and I'm please with progress.  
A decision =eeds to be made on the fuel tanks. At this time the tanks are not leaking =ut will in the near future.

After extensive cleaning the bottom of the tan= has many large pits that will soon start to leak.

The condition of the tanks most likely were caused by not having a prop=r sealing of the deck fuel fitting  
allowing salt water to enter the tank a=d do its damage.

These fittings were placed on the d=ck ,in our quote we would have a stand pipe above the deck next to t= the  
wheel house so this problem will not happen again. We will ne=d a answer soon so work will not be delayed any longer  
than necessary.

Please visit or call wit= any concerns.

Thanks

Gene =AO

Gene Kral Sr.

Subbase Drydock, Inc.

Parcel 162, Subbase =br>St. Thomas, USVI 00802

TEL: [REDACTED]

FAX: [REDACTED]

[www.subbasedrydock.com](http://www.subbasedrydock.com) <http://www.subbasedrydock.com>

=img src="cid:28A3C97B-9873-47BE-B1A6-3A9D5C7F9E09" alt="image1.JPG">

--

=AO please note

The information contained in this commu=ication is confidential, may be attorney-client privileged, may cons=titute  
inside information, and is intended only for the use of the addre=see. It is the property of JEE Unauthorized use,  
disclosure or copyi=g of this communication or any part thereof is strictly prohibited a=d may be unlawful. If you have  
received this communication in error, pl=ase notify us immediately by return e-mail or by e-mail to

jeevacation@gmail.com, a=d destroy this communication and all copies thereof, including all a=tachments. copyright -all rights reserved