

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Monday, March 19, 2018 3:33 PM  
**To:** Jeffrey  
**Subject:** Je vacation  
Pocket door

Jeffrey

Take 1.5 weeks or 10 days to re-Veneer the pocket door cabin side.,

The spare veneer is currently in Savannah, I was getting ready to ship to Is=ip, It may be best to have savanna accomplish the Re-veneer on pocket door since=their finishing process may differ from Eric's, such as we saw with=the silver birch finish., We can remove the pocket door and fly without and use the fwd lav door to is=late cockpit area from the cabin temporarily.

When ever you elect to accomplish re-veneer of pocket door.

Just a thought

Thx  
Larry

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">  
<plist version=.0">  
<dict>  
    <key>conversation-id</key>  
    <integer>12039</integer>  
    <key>date-last-viewed</key>  
    <integer>0</integer>  
    <key>date-received</key>  
    <integer>1521473583</integer>  
    <key>flags</key>  
    <integer>8590195717</integer>  
    <key>gmail-label-ids</key>  
    <array>  
        <integer>6</integer>  
        <integer>2</integer>  
    </array>  
    <key>remote-id</key>  
    <string>805560</string>  
</dict>  
</plist>