

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Monday, March 19, 2018 10:51 PM  
**To:** Je vacation  
**Subject:** G550 Update

Jeffrey

1-Interior shop informs, there is a Plastic STOP located on seat swivel fram=,.  
He could not show exactly its location, since the seat base has to be taken a=art. He can't remove the STOP since the seat base is located by an e=ergency Exit window,. I feel confident Pete or Eric could remove this STOP f=om Seat base this week in NY,

2-almost done with ALL Tray table lid adjustments 3-Pocket Door adjustment is working well.,  
4-VIP lid and Rear LID to house the phones will be worked tomorrow 5-still working latches, and Galley door adjustments  
6-we gwill cover Red /Green slider 7-installed shim on Main entrance door handle

If all goes well, we are planning a test flight at 3PM if you approve?

Thx  
Larry

the 46" OLED TV and Apple TV is in Teterboro, should load on the G55=

Sent from my iPad=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"  
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">  
<plist version=.0">  
<dict>  
    <key>conversation-id</key>  
    <integer>12053</integer>  
    <key>date-last-viewed</key>  
    <integer>0</integer>  
    <key>date-received</key>  
    <integer>1521499844</integer>  
    <key>flags</key>  
    <integer>8590195717</integer>  
    <key>gmail-label-ids</key>  
    <array>  
        <integer>6</integer>  
        <integer>2</integer>  
    </array>  
    <key>remote-id</key>  
    <string>805724</string>  
</dict>  
</plist>