
From: Alireza Ittihadieh [REDACTED]
Sent: Thursday, March 15, 2018 2:29 PM
To: jeffrey E.
Subject: RE: 1085

Can I get the Below Updated

Airframe

9,500 Hours TTSN

4,326 Landings

On GCMP (Computerized Aircraft Maintenance Program)

Engines

Rolls Royce Tay MK 611-8

Engine 1 (L) s/n 16291

15,639 hrs TSN

Engine 1 since overhaul

1,820 hrs SMOH

Engine 2 (R) s/n 16292

16,840 hrs TSN

Engine 2 since overhaul

1,820 hrs SMOH

TBO

8,000 hrs

Enrolled on Rolls Royce Corporate Care

APU

??? Hrs TTSN

Garrett GTCP 36-150 installed in 2013

????

Thanks

V-BR

Alireza ITTIHADIEH

✉:

✉:

From: jeffrey E. [mailto:jeevacation@gmail.com]

Sent: Monday, August 14, 2017 5:54 PM

To: Alireza Ittihadieh

Subject:

<<https://mail.google.com/mail/u/0/images/cleardot.gif>>

Gulfstream Palm Beach did DU885 upgrade.

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved