

---

**From:** Lvjet <[REDACTED]>  
**Sent:** Saturday, January 17, 2015 6:42 PM  
**To:** jeevacation@gmail.com  
**Subject:** flap

your thoughts,?

inboard actuator has hard spot to turn,. can't really determine if this is the bad unit,. I have Both actuators in ST=,. should be warrentee item since we 24 month warrentee,. however, if I change both, we may be liable for one unit,. =hey are \$39k each,