
From: [REDACTED]
Sent: Thursday, April 4, 2013 12:01 PM
To: Je vacation
Subject: Re: gIV

Jeffrey,
I confirm friday 6pm wheels up.

I should have more info afternoon today, the measurement of crack length has been presented to RollsRoyce and Cooperate Care for determination if either Engines cracks are beyond limits.

More info later today,

Possible options:

- Best scenario remove both engines and send for repair.
- cracks in burner can may be acceptable and with-in factory limits and we push fwd.
- Rolls Royce may elect to issue a "TV" technical variance" which requires a future borescope at some point.

These engines are on Cooperate Care program, its Rolls Royce's call on future requirements of these engine inspections if they pass these engines.,

More info later

Thx
Larry
Sent via BlackBerry by AT&T

From: Jeffrey Epstein <jeevacation@gmail.com>
Date: Thu, 4 Apr 2013 07:51:15 -0400
To: [REDACTED]
Subject:

what happened yesterday

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved