
From: Scott Denett <[REDACTED]>
Sent: Wednesday, April 27, 2011 4:29 PM
To: J Epstein
Cc: Richard Kahn
Subject: 71st 6th floor

Had a conversation with nick yesterday and we both agree that the issue is most likely not the subs but the mains.

The reasoning behind this is

1

when we got there the main speakers were blown

2

the subs are only on level 2 out of 10 (the calibration software put the level at .09 I had nick raise it to 2 to give you some push but i fully understand you want more)

Your new sunfire is incredibly powerful 400 watts a channel (thats huge!)

those jbl will never take the power of that amp at full volume that is why I had nick cap the max volume so the speaker are less likely to blow

I wish we had had a chance to review this in person getting new mains and turning the volume up on the subs is prob the best solution.

I know you have issues with the projector at LSJ so getting nick to swap that HAS major value after you taken care of there, I would like to work with you on how to resolve the sixth floor with or without nick nick and i are CURRENTLY working well together just FYI

your long term AV needs is my main concern and I am ready for the challenge no matter what vendor you are using at that time.

thank you

Scott

```
<?xml version="1.0" encoding="UTF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version="1.0">
```

```
<dict>
  <key>conversation-id</key>
  <integer>185572</integer>
  <key>date-last-viewed</key>
  <integer>0</integer>
  <key>date-received</key>
  <integer>1303921788</integer>
  <key>flags</key>
  <integer>8590195713</integer>
  <key>gmail-label-ids</key>
  <array>
    <integer>6</integer>
    <integer>2</integer>
  </array>
  <key>remote-id</key>
  <string>151851</string>
</dict>
</plist>
```