
From: [REDACTED]
Sent: Saturday, September 3, 2011 12:45 AM
To: Je vacation
Cc: Emad Fakhry Hanna
Subject: Hanger door

Jeffrey,

.
Generator is not required for stt hanger if we do not install a bi-fold eletric door. I think bi-fold door is not cost effective, need to modify existing door which would eliminate generator requirement during power outages at airport.

Sent via BlackBerry by AT&T

```
<?xml version="1.0" encoding="UTF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version="1.0">
<dict>
    <key>conversation-id</key>
    <integer>198300</integer>
    <key>date-last-viewed</key>
    <integer>0</integer>
    <key>date-received</key>
    <integer>1315010678</integer>
    <key>flags</key>
    <integer>8590195713</integer>
    <key>gmail-label-ids</key>
    <array>
        <integer>6</integer>
        <integer>2</integer>
    </array>
    <key>remote-id</key>
    <string>177834</string>
</dict>
</plist>
```