
From: Carlos Rodriguez <[REDACTED]>
Sent: Wednesday, November 8, 2017 3:54 PM
To: Richard Kahn; jeffrey E.; Ann Rodriguez; Daphne Wallace
Subject: Chris boat revised

Greetings all, i spoke to offshore this morning and they explained to me we need all new controls, keys throttles and comm box since the 300 are totally electronic motors. The additional cost is 4524.88, plus install which brings the total to at least 12,500 and the motor is not new. A new 150 is 14,686 dollars, plus install. Please advice, I apologize for not realizing the harnesses were not compatible.

The used 300 could be a great spare motor for us still. Please advice if we should purchase.

Thankyou

Respectfully

Carlos

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>25174</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1510159783</integer>
 <key>flags</key>
 <integer>8590195717</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>6</integer>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>766621</string>
</dict>
</plist>