
From: [REDACTED]
Sent: Friday, August 2, 2013 3:07 PM
To: Je vacation
Subject: GII repair

Jeffrey,

The Brake accumulator is still leaking on GII. We are arranging for Gulfstream in Las Vegas to change this part on arrival. 6 hours to accomplish. This was changed while plane was in NY, still leaking, its a simple system. Having new accumulator fedex to Vegas for gulfstream to install for warrenty, not a safety of flight, its parking brake accumulator.

Just fyi.

Sent via BlackBerry by AT&T

```
<?xml version="1.0" encoding="UTF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version="1.0">
<dict>
  <key>conversation-id</key>
  <integer>262728</integer>
  <key>date-last-viewed</key>
  <integer>0</integer>
  <key>date-received</key>
  <integer>1375456036</integer>
  <key>flags</key>
  <integer>8623750145</integer>
  <key>gmail-label-ids</key>
  <array>
    <integer>6</integer>
    <integer>2</integer>
  </array>
  <key>remote-id</key>
  <string>329573</string>
</dict>
</plist>
```