
From: Jeffrey Epstein <jeevacation@gmail.com>
Sent: Thursday, February 13, 2014 10:50 PM
To: Eric Roth
Subject: Re: Acoustic Material cost / direction

do the insulation just saw the picture

On Thu, Feb 13, 2014 at 9:52 PM, Eric Roth <████████<mailto:████████>> wrote:

Jeffrey,=p>

As requested, we can further insulate the exposed areas at the main cabin area window line and lower side panels. Further, we would insulate open pocket areas in the main cabin area window line that exist randomly through=ut.

You were partially correct in your assessment - you ma= have heard noise coming from the L/H fwd seat outboard area, but it was n=t from the headliner - it was most likely from the window line area where =here was absolutely no insulation at all (an open pocket between ribs, exp=ed to the fuselage skin).

Please note that the headliner panels and the valence =anel have been previously treated with an acoustical barrier material lam=nated directly to the panels.

As noted in my prior e-mail, the cabin area windows ar= not well insulated and have bare exposed fuselage. This would be treat=d as per the open cellular acoustic foam.

The window line and lower side panels would be treated=with two (2) different acoustical materials:

A high performance vibration dampening material would =e adhered directly to the composite lower side, window line and headlin=r panels. This composite dampening material is very effective at reduci=g the airborne sound generated by vibration of these panels.=span>

Additionally, we will also incorporate an=Aeroblanket which consists of one layer of an Aerobarrier material bonded =o one layer of Nomex fiber. This over frame blanket i= used to close out the insulation and prevent= a direct path for sound to penetrate into the cabin.

<= class="MsoNormal">More specifically, the AeroBar=ier component of the blanket is highly effective in reducing overall sound=levels and the fiber is very effective at reducing high frequency sound le=els.

The cost to procure and install these materials is \$16=870.

Please let me know if you would like us to install the=e acoustical dampening materials so that we can order them ASAP and ship o=ernight or if not, allow us to continue reinstallation of the interior.=/u>

PS - good news - 3 new light bulbs all=of the same series part number did the trick - we will monitor the lights =ever the next few days to make sure there is not a weak power supply / ball=st.

Warm regards,

Eric

ERIC H. ROTH =span style="font-size:9.0pt;font-family:"Arial","sans-ser=f";color:#644e39"> | PRESIDENT

<=>

2221 S=ithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=>

<=div>

--
*****=_*****

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved