

---

**From:** Eric Roth <[REDACTED]>  
**Sent:** Friday, March 14, 2014 8:35 PM  
**To:** Jeffrey Epstein  
**Cc:** Larry Visoski  
**Subject:** GIV

Jeffrey,

We were not able to get the wire through the bulkhead on the L/H side during this visit as we found that more of the interior needs to be removed than anticipated.

We were however able to go through the bulkhead on the R/H side in your direct view.

All other items were completed including providing you with a second remote (what was programmed) so that should your remote get damaged, lost, etc. down the road, you had a back up ready to go.

Lastly, we installed a cool white and a warm white led for you to view on your flight.

Eric

ERIC H. ROTH | PRESIDENT

[REDACTED] | C [REDACTED]  
[REDACTED] | intljet.com=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">  
<plist version=.0">  
<dict>  
    <key>conversation-id</key>  
    <integer>284881</integer>  
    <key>date-last-viewed</key>  
    <integer>0</integer>  
    <key>date-received</key>  
    <integer>1394829316</integer>  
    <key>flags</key>  
    <integer>8590195713</integer>  
    <key>gmail-label-ids</key>  
    <array>  
        <integer>6</integer>  
        <integer>2</integer>  
    </array>  
    <key>remote-id</key>  
    <string>396024</string>  
</dict>  
</plist>