
From: jeffrey E. <jeevacation@gmail.com>
Sent: Wednesday, October 8, 2014 5:54 PM
To: Brice Gordon
Subject: Re: ZDC-HWS Repair.

thanks i see it doesn't work well have j=j=try to match current and just repair. cut out enought so it de=ns't look funky

On Wed, Oct 8, 2014 at 1:36 PM, Brice Gordon zdc.rt41@gmail.com [REDACTED] > wrote:

Jeffrey

Attached photo's of proposed area for con=rete removal.

To confirm

We n=ed to cut out concrete to garage floor on both 1 and 3 bays due to the cra=k running across the entire length of garages.

I am assuming tha= the final result is for both pads 1 and 3 to centered on each opening and=to match in size can we proceed.?

<=div>

Brice Gordon
49=Zorro Ranch Rd
Stanley, NM 87056

Ph: [REDACTED]

--

=C2◆ please note

The information co=tained in this communication is confidential, may be attorney-client pr=vileged, may constitute inside information, and is intended only for

JEE

Unauthorized use= disclosure or copying of this communication or any part thereof is str=ctly prohibited and may be unlawful. If you have received this commu=ication in error, please notify us immediately by return e-mail or by e=mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and all copies thereo=,

including all attachments. copyright -all rights reserved

</=iv>