
From: jeffrey E. <jeevacation@gmail.com>
Sent: Thursday, November 13, 2014 12:41 AM
To: Larry Visoski
Subject: Re: Heli

yes

On Wed, Nov 12, 2014 at 8:14 PM, Larry Visoski <[REDACTED]> =gt; wrote:

Jeffrey,

During engine start up on LSJ tonight my #1 AutoPilot failed., our Bell 430=is equipped with two digital autopilots, I selected #2 autopilot and all w=s fine, the passengers didn't notice anything was wrong, it was a good=flight.

The autopilot is engaged before departure for SCAS system. (Stability Contr=l Augmentation System). The 430 can fly safely without AP working as well.=I practice this when your not in the helicopter.

I swapped Autopilot computers and the failure followed, so it's a simpl= AP Box change. I will bring the AP computer box when I return to Fla and =locate exchange unit, 30min install only.

Is it Ok to airline home tomorrow ?

Thank you
Larry

Sent from my iPhone

--

=C2 please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee=. It is the property of JEE Unauthorized use, disclosure or copying =f this communication or any part thereof is strictly prohibited and =ay be unlawful. If you have received this communication in error, please= notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and<=r>destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved