
From: Larry Visoski [REDACTED]
Sent: Friday, January 11, 2019 2:50 PM
To: Je vacation
Cc: Rich Kahn; Lesley Groff
Subject: G550 issue

Jeffrey

Pete just installed the Battery control relay, per Tech support in Savannah, ,=it Did Not fix our issue of #2 battery coming on line,, Avionics Tech support From Westfield is driving to Teterboro is the plan, w= could be delayed for departure tomorrow., I'm still in PBI with Dave, If your trip to LSJ is urgent, should I bring the GIV to Teterboro today? Or=continue to Airline up now?

Airline or GIV?

Thx
Larry

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>

<key>conversation-id</key>
<integer>316212</integer>
<key>date-last-viewed</key>
<integer>0</integer>
<key>date-received</key>
<integer>1547218183</integer>
<key>flags</key>
<integer>8590195713</integer>
<key>remote-id</key>
<string>889808</string>

</dict>
</plist>