

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Friday, January 11, 2019 5:49 PM  
**To:** Je vacation  
**Cc:** Rich Kahn  
**Subject:** G550 update

Jeffrey

The G550 is working normal now,  
Pete disconnected the Left Battery, turned on the external battery switch, and the R/H battery came on line normal, he proceeded to hook up the L/H battery, and all battery's stayed on line.,  
He Shut down the plane completely, and turned both battery's on,,, and was normal, Only a guess, since you recommended to look at the battery contacts, I =99m guessing, the plane needed to energize or Pull a Battery relay closed, after the install of the New Battery Control Relay, Westfield is still going to come to Teterboro to review all what Pete troubleshoot, to make sure we are good.,

Dave and I will Arrive Newark tonight at 8pm,..  
All is a go for LSJ tomorrow at this time .,

Let me know when you want wheels up to LSJ tomorrow?

Thx  
Larry

Sent from my iPad=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"  
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">  
<plist version=.0">  
<dict>  
    <key>conversation-id</key>  
    <integer>316239</integer>  
    <key>date-last-viewed</key>  
    <integer>0</integer>  
    <key>date-received</key>  
    <integer>1547228918</integer>  
    <key>flags</key>  
    <integer>8590195713</integer>  
    <key>remote-id</key>  
    <string>889865</string>  
</dict>  
</plist>