

---

**From:** Richard Kahn <[REDACTED]  
**Sent:** Thursday, December 27, 2018 10:07 PM  
**To:** brice gordon  
**Cc:** jeevacation@gmail.com  
**Subject:** Re: LSJ Cabana 3

brice why now are you suggesting a certified plumber when proj=ct is months past due.

<=iv id="AppleMailSignature" dir="ltr">

HBRK Associates I=c.

[REDACTED]=div>  
New York, NY 10022

Update

By Friday=afternoon Cabana's 1 and 4 will be ready

At this time=both Cabana's 2 and 3 have plumbing issues, fortunately Cabana 2 di= not sustain damage But a bigger issue was discovered=this afternoon, it appears there is a leak in the supply line from the mani=old under Cabana 1 to Cabana's 2 and 3.

Please note=this line is original to build.

Regarding the question of respons=bility For the hot water line - JPK Yes, th=s was the first time cabana's 2 and 3 sustain constant water p=essure to bathrooms LSJ plumbed vanities and hot water heat=rs .

Comments

Fin= certified plumber !!!

If possible Run a camera thru lines ??

Order wall tile for showers ASAP.

Schedule AHF again f=r floor repairs in cabana 3 We need to be absolutely =confident in plumber and tile for master bath Reno before moving forward&nbs=;

Brice

<=iv>

=div>

<=iv>

Sent from m= iPhone

On Dec 27, 2018, at 3:57 PM, Richard Kahn=<[REDACTED]> &=t;  
wrote:

Brice / Kyle=nbsp;

Thanks for update. Who's is responsible fo= this hot water line? Was jay involved? Our crew? Was this the f=rst time water was tested? Please advise. Thank you.

R=chard Kahn  
HBRK Associates In=.  
[REDACTED] /=iv>  
New York, NY 10022

<IMG\_3233.jpg>

<=r>

<IMG\_3239.jpg>

Sent from my iPhone

=/body>  
=