
From: J <jeevacation@gmail.com>
Sent: Friday, October 19, 2018 1:45 PM
To: Kyle reavis; Richard Kahn
Subject: Re: Generator building Rust

did you just descibe that door as having a rust "spot=quot;

On F=i, Oct 19, 2018 at 8:58 AM Kyle reavis <[REDACTED]> <mailto:[REDACTED]> > wrote:

Mr Epstein,

The doors and door hardware all have rust spots. Vents have rus= along with the leavouts for the new exhaust vents.

Kyle

--

=C2 please note

The information co=tained in this communication is confidential, may be attorney-client pr=vileged, may constitute inside information, and is intended only for

JEE

Unauthorized use= disclosure or copying of this communication or any part thereof is str=ctly prohibited and may be unlawful. If you have received this commu=ication in error, please notify us immediately by return e-mail or by e=mail to jeevaca=ion@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and all copies thereo=, including all attachments. copyright -all rights reserved

</=iv>

--0000000000002a317b0578951da5-- conversation-id 324801 date-last-viewed 0 date-received 1539956717 flags 8590195713 remote-id 863967