
From: Eric Roth [REDACTED]
Sent: Wednesday, September 5, 2018 6:15 PM
To: Jeffrey E.
Subject: BBJ2 VP-CBB

<=span>

Jeffrey,

For very rough, budgetary purposes, I =believe you could use similar numbers to what we provided you 2 yrs ago for=BBJ 30884.

The reality is you will never want to =ust simply recover what is there. You (and I) will look at most any =rea and then start to add details.

I believe when all is said and done, m= gut tells me that you will likely find the cost to refurbish the existing=interior (plus remove some seating to get you to 19 passenger occupancy) including all soft goods, woodwork and =etal plating, somewhere between \$3.75M to \$5.0M.

If you were to get your friendly frogs=dressed in gold corduroy's from across the pond involved, add anothe= \$1M plus...? For the additional details and wood that will not make you sad.

This does not include entertainment sy=tems, cabin management systems, etc.

Best Regards,

ERIC H. ROTH<=> | PRESIDENT



2221 S=ithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=:p>