

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Saturday, February 2, 2019 1:30 AM  
**To:** Je vacation  
**Cc:** Rich Kahn  
**Subject:** G550 Mx  
**Attachments:** image1.jpeg; Untitled attachment 00098.txt

Jeffrey

Pete will be changing a slide in PC computer cards in the MAU (Multiple Avionics Unit) on the G550 tomorrow, easy install, just takes time to reload the software after install.,

When Pete Powered up the G550 the #1 FMS reverted to StBy engine instruments= which is the backup Function of the #1 FMS in case of power failure, Pete spoke with Tech Support And was advised:

It's one of the computer cards in the Multiple Avionics Units (MAU) that is not sending the FMS Data to the Display. Default is backup engine instruments.

Part arrives Teterboro tomorrow morning

Thx  
Larry

#1 FMS displaying engine instruments,