

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Wednesday, September 6, 2017 3:03 PM  
**To:** Je vacation  
**Subject:** Update  
**Attachments:** IMG\_2796.JPG; Untitled attachment 00239.txt; IMG\_2802.JPG; Untitled attachment 00242.txt

Jeffrey  
Low Trim Valves installed,  
PAC Temp output constant at 35° full cold and full hot,.  
Good fix,,  
Still working #2 HF radio,,  
We have Swapped the RT's and issue remained on #2 HF, Tech is speaking to te=h ops in Savanah looking into fiber optics and other areas of HF,,

Question:  
Do you want Eric to fabricate leather armrest covers like GIV?

Thx  
Larry