
From: Richard Kahn <[REDACTED]>
Sent: Friday, April 5, 2019 9:13 PM
To: Jeffrey Epstein
Subject: Fwd: Oil Room

Richard Kahn
HBRK Associates Inc.
575 Lexington Avenue 4th Floor
New York, NY 10022
[REDACTED]

Begin forwarded message:

From: Michael Glidden <[REDACTED]>
Subject: Re: Oil Room
Date: April 4, 2019 at 11:26:30 AM EDT
To: Richard Kahn <[REDACTED]>

No leak in a fuel tank. Improperly stored used oil that worked its way through a crack in the floor to the tank room below.

Going forward all used oil will be properly stored and containment pallets will be set properly.

On Thu, Apr 4, 2019 at 10:09 AM Richard Kahn <[REDACTED]>
> wrote:

do we have a leak in the fuel tank?
please advise
thank you

Richard Kahn
HBRK Associates Inc.
575 Lexington Avenue 4th Floor
New York, NY 10022



Begin forwarded message:

From: Cashkim Bussue <>

Date: April 3, 2019 at 3:53:14 PM =DT

To: jeevacation@gmail.com

Cc: 

Attached are images coming from inside the oil Room with cracks on the floor which I presume is the reason for the leakage inside the Fuel tank.

Sent from my =Phone

=