

---

**From:** Larry Visoski [REDACTED]  
**Sent:** Tuesday, September 5, 2017 11:42 AM  
**To:** jeffrey E.  
**Subject:** Re: Duct temps

Yes

Your correct, I re=ember that as well,. I didn't take a photo of that.,

All of this information should be recorded on the FDR (Flight Data Record=r) in the aircraft that can be downloaded by Gulfstream.,

I=will speak with Rusty and inform, this is unacceptable, we have only flown e=actly 49 hours since prebuy in March on G550.

Sent from my iPhone

On Sep 5, 2017, at 1:=3 PM, jeffrey E. <jeevacation@g=ail.com <mailto:jeevacation@gmail.com> > wrote:

yes but the third one was reading 94 then 92 then 94 . &=nbsp; it came down to 84 but chip and I were watching the aft one =

On Tue= Sep 5, 2017 at 1:12 PM, Larry Visoski [REDACTED] wrote:  
=blockquote class="gmail\_quote" style="margin:0 0 0 .8ex; border-left:1px=#ccc solid; padding-left:1ex">Duct temps read;

Mid cabin duct 81 degrees

Aft cabin duct 84 degrees

Pac outlet temp;

Outlet PAC temps

L/H PAC outlet temp 74

R/H PAC outlet temp 80

Sent from my iPhone

--

<=div class="gmail\_signature" data-smartmail="gmail\_signature">  
please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this

return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com>, and destroy this communication and all copies thereof, including all attachments. Copyright - all rights reserved

=/div>

=